


TECHNICAL DUE DILIGENCE REPORT


20-28 Sir William Pickering Drive,
Christchurch

Reliant Parties:
Augusta Funds Management Limited

Date: 27th November 2017
CBRE Ref: 49211286

CBRE





CONTENTS

| | | |
|--------------|--|----|
| 1 | EXECUTIVE SUMMARY | 4 |
| 2 | SYNOPSIS | 5 |
| 3 | RELIANCE & REPORTING | 6 |
| 4 | BUILDING DESCRIPTION | 7 |
| 5 | STRUCTURE | 9 |
| 6 | BUILDING FABRIC | 13 |
| 7 | EXTERNAL AREAS | 25 |
| 8 | MECHANICAL SERVICES | 28 |
| 9 | ELECTRICAL SERVICES | 34 |
| 10 | FIRE SERVICES | 37 |
| 11 | HYDRAULIC SERVICES | 39 |
| 12 | VERTICAL TRANSPORTATION SERVICES | 40 |
| ATTACHMENT 1 | CAPITAL EXPENDITURE REPORT | 42 |
| ATTACHMENT 2 | EXCLUSIONS & QUALIFICATIONS | 46 |
| ATTACHMENT 3 | TERMS & CONDITIONS | 47 |

1 EXECUTIVE SUMMARY

- 20-28 Sir William Pickering Drive comprises two standalone office blocks within a large site close to Christchurch Airport. The original 'Andy Herd' building was constructed circa 1987, the property is described as a commercial office building providing approximately 2,257m² of lettable office space set over two levels. The New Airways Building was built circa 1992 and extended to add the Airways Development Centre c2007, the property is described as a commercial office building providing approximately 5,095m² combined lettable office space set over two stories at ground and first floor level.

KEY ISSUES

| ELEMENT | COMMENT | TIME FRAME |
|--------------------------------|--|-------------|
| STRUCTURE | No major concerns identified. | |
| BUILDING FABRIC | Replace felt roof coverings to building 1 at end of useful life. | EXTENDED |
| | Replace floor covings at end of useful life. | EXTENDED |
| | Replace suspended ceilings at end of useful life. | EXTENDED |
| | Cyclical external decoration required. | EXTENDED |
| EXTERNAL AREAS | No major concerns identified. | |
| MECHANICAL SERVICES | Replace chillers at the end of their useful life. | EXTENDED |
| | Process Cooling / CRAC units appear in good condition but will need overhauled. | LONG to EXT |
| | VRV plant appears in good condition, practically new. Replacement will be required in the extended reporting period. | EXTENDED |
| | Replace other packaged AC plant as the units fail. | LONG |
| ELECTRICAL SERVICES | Overhaul MSB's & DB's at the end of economic life | EXTENDED |
| | Some concerns with exit signage locations - reposition as required. | SHORT |
| FIRE SERVICES | Replace FIP at the end of economic life | LONG to EXT |
| | Replace the sprinkler tank at end of economic life. | EXTENDED |
| | Overhaul Boosters, valve sets and hydrants. | LONG to EXT |
| HYDRAULIC SERVICES | Replace the water header tanks on the roof | MEDIUM |
| | Replace hot water systems as they fail | MED- LONG |
| VERTICAL TRANSPORTATION | Overhaul lift at the end of economic life. | LONG to EXT |


TIMEFRAME IMMEDIATE SHORT (1-2 YRS) MEDIUM (3-5 YRS) LONG (6-10 YRS) EXTENDED (11-25 YRS)

RISK RATING HIGH MODERATE LOW


FINANCIAL SUMMARY

| | Immediate | Short Term (1-2 years) | Medium Term (3-5 years) | Long Term (6-10 years) | Extended Term (11-25 years) | Total |
|-----------------------------|-----------------|------------------------|-------------------------|------------------------|-----------------------------|---------------------|
| 1.0 STRUCTURE | \$ - | \$ - | \$ - | \$ - | \$ 15,000 | \$ 15,000 |
| 2.0 BUILDING FABRIC | \$ 3,500 | \$ - | \$ - | \$ - | \$ 1,400,000 | \$ 1,403,500 |
| 3.0 EXTERNAL AREAS | \$ - | \$ - | \$ - | \$ - | \$ 25,000 | \$ 25,000 |
| 4.0 MECHANICAL SERVICES | \$ - | \$ - | \$ - | \$ 175,000 | \$ 983,000 | \$ 1,158,000 |
| 5.0 ELECTRICAL SERVICES | \$ - | \$ 5,000 | \$ - | \$ - | \$ 300,000 | \$ 305,000 |
| 6.0 FIRE SERVICES | \$ - | \$ - | \$ - | \$ 45,000 | \$ 70,000 | \$ 115,000 |
| 7.0 HYDRAULIC SERVICES | \$ - | \$ - | \$ 20,000 | \$ 10,000 | \$ 20,000 | \$ 50,000 |
| 8.0 VERTICAL TRANSPORTATION | \$ - | \$ - | \$ 180,000 | \$ - | \$ 180,000 | \$ 360,000 |
| TOTAL | \$ 3,500 | \$ 5,000 | \$ 200,000 | \$ 230,000 | \$ 2,993,000 | \$ 3,431,500 |

TIMELINE



ELEMENTAL



2 SYNOPSIS

2.1 INSTRUCTIONS

- Instructions:**
- Written instructions received from:
 - Augusta Funds Management Limited
 - Instruction established from quote issued on 29th September 2017.
- Assessment**
- Technical Due Diligence review of:
- Request:**
- 20-28 Sir William Pickering Drive, Christchurch
- Reliant Parties:**
- Augusta Funds Management Limited
- CBRE Reference:**
- K:\Valuations\BDCC\18 - Building Consultancy\3. Christchurch\Sir William Pickering Drive\6. Reports
- Scope of service:**
- Structure
 - Building Fabric (roofs, facades & interior)
 - External Areas
 - Building Services (Mechanical, Electrical, Fire, Hydraulics & Lifts)
 - Extended 25 Year Capital Expenditure (CAPEX) Forecast

2.2 CRITICAL ASSUMPTIONS

- Information Supplied by Others:**
- This report contains information which is derived from other sources. Unless otherwise specifically instructed by you and/or stated in the report, we have not independently verified that information, nor adopted it as our own, or accepted its reliability. The Reliant Party accepts the risk that if any of the unverified information/advice provided by others and referred to in this report is incorrect, then this may have an effect on our review. Documentation, information etc. relied upon is noted within the main body of this report.
- Changed Information:**
- In the event that the Reliant Party becomes aware of any material changes to the property and/or that information supplied to us is incorrect, then this report must not be relied upon before first consulting CBRE to provide a review of the updated information.

3 RELIANCE & REPORTING

3.1 RELIANCE & LIABILITY

- Reliance:** ■ This assessment is strictly and only for the use of the Reliant Parties and for the Purpose specifically stated in Synopsis/Instructions.
- Transmission:** ■ Only an original report received by the Reliant Party directly from CBRE without any third-party intervention can be relied upon.
- Restricted:** ■ No responsibility is accepted or assumed to any third party who may use or rely on the whole or any part of the content of this assessment.
- Copyright:** ■ Neither the whole nor any part of the content of this report may be published in any document, statement, circular or otherwise by any party other than CBRE, nor in any communication with any third party, without the prior written approval from CBRE, and subject to any conditions determined by CBRE, including the form and context in which it is to appear.

3.2 REPORTING

- Industry Practice:** ■ Our review has been undertaken in line with the RICS best practice guidance note on Technical Due Diligence of Commercial & Industrial Property (New Zealand).
- Inspection:** ■ The inspection was carried out on Friday 27th October 2017.
■ Roof access was available onto both buildings via internal stairs/roof hatches.
■ The façade was inspected from roof areas, internally from office areas, and from ground level only.
■ Access was generally not available to the female amenities during the inspection however a representative sample of male amenities were inspected.
- Orientation:** ■ References to the left and right-hand side assume the reader is facing the element in question. The site is deemed to be facing east, fronting Sir William Pickering Drive.
- Weather:** ■ The weather at the time of inspection was dry and overcast after periods of rain.
- Limitations:** ■ Refer to the Attachments for our standard reporting Exclusions & Qualifications and Terms & Conditions.
- Prepared by:** ■ **Benjamin Walker MRICS** | Associate Director
■ P +64 9 359 5293 | M +64 27 300 0088 | ben.walker@cbre.co.nz
■ **Phillip Carruthers** | Engineering Services Manager
■ P +61 7 3833 9098 | M +61 407 113 749 | phillip.carruthers@cbre.com.au
- Reviewed by:** ■ **Stewart Cavin MRICS** | National Director
■ P +61 7 3239 9928 | M +61 437 464 831 | stewart.cavin@cbre.com.au
- Issue:** ■ Final Report

4 BUILDING DESCRIPTION

4.1 GENERAL DESCRIPTION

- 20-28 Sir William Pickering Drive comprises two standalone office blocks within a large site close to Christchurch Airport.
- The original building (The Andy Herd Building - hereafter referred to as building 1) was constructed circa 1987, the property is described as a commercial office building providing approximately 2,257m² of lettable office space set over two stories at ground and first floor level.
- The main building on the site (New Airways Building) was built circa 1992 and extended circa 2007 (Airways Development Centre), the property is described as a commercial office building providing approximately 5,095m² combined lettable office space set over two stories at ground and first floor level. The building also has lading bay and garage areas. (Hereafter, main building and extension will be referred to as building 2)
- Building 1 is more fully described as Lot 2 in DP 375305 with a site area of 5,900 m².
- Building 2 is more fully described as Lot 1 DP 71767 / Lot 7 DP 54647 which we understand is a standard format lot with a site area of 11,413 m².
- The site is broadly rectangular in shape being bounded by Sir William Pickering Drive to the east and a variety of commercial/industrial properties to the immediate north, south and east although the buildings are situated in a wider residential area.
- The main pedestrian entry into the site is off Sir William Pickering Drive and entry to building 1 is gained from the south elevation whilst entry in to building 2 is gained via doors to the north elevation. The entry is via glazed double doors giving access to the ground floor entrance vestibule and foyer.
- Car park entry is off Sir William Pickering Drive.
- Within building 1 there is a single stair core to the east side of the building, this stair core also contains a single passenger lift which provides access between ground and first floor.
- Within the original part of building 2, there is a single stair core to the south end of the building with no passenger lift. The more recent extension now provides an additional 2 stair cores, one with the reception lobby area and one to the east side of the building. The reception area also houses a single passenger lift which provides access between ground and first floor.
- The layout on each floor generally comprises cellular offices and densely fitted out office space.
- Building 2 was extended approx. 10 years ago to provide new entrance vestibule, lobby, reception area and additional office space on the ground and first floor. The building has been progressively refurbished a number of times since construction.
- The most significant refurbishments have occurred c.2007 at the same time as the new Airways Development Centre was built, which we understand broadly entailed;
 - New carpets, lighting to some areas and full redecoration.
 - New kitchen & food prep facilities.
- The Building Warrant of Fitness is located in the ground floor foyer and dated 27th September 2017, with no outstanding items.

4 BUILDING DESCRIPTION

4.2 SCHEDULE OF PLANT & EQUIPMENT

| SCHEDULE OF PLANT & EQUIPMENT | | | |
|-------------------------------|-------------------|-------------------|-----------|
| Item of plant | Number/Type | Date Installed | Condition |
| Chillers | Aermec | Circa 2015 & 2017 | Good |
| CRAC's | Stultz & Emmerson | Various | Good |
| Packaged AC | Daikin | Various | Good |
| Lifts | Unknown | Original | Fair |

5 STRUCTURE

5.1 SUMMARY OF ISSUES & OBSERVATIONS

- The structural elements where visible were noted to be generally in good condition with no major issues or concerns identified.
- No significant movement in the structural frame or walls was observed to suggest possible foundation problems; however, any minor movement should be monitored periodically as recommended below.
- Minor plastic shrinkage cracking was observed to localised areas of the driveways. Although these are not of immediate concern, we recommend all cracking be monitored to identify progressive movement, should it occur. Crack repairs can be carried out thereafter.
- No obvious signs of any significant water ingress were noted during our inspection.

5.2 GENERAL DESCRIPTION

- The substructure was fully concealed at the time of inspection and no 'as built' information has been provided. However, based on our visual inspection and knowledge of buildings of a similar nature, we anticipate the substructure to comprise of a footing system as follows:
 - Concrete strip foundations which supports external concrete walls and columns, re-enforced concrete slab supporting internal columns and concrete piers
 - The floor slabs to both ground and first floor are cast in-situ reinforced concrete. The first floor is supported by a series of internal columns and perimeter re-enforced masonry piers. Although not sighted due to soffit linings we assume some form of drop beam or band beam arrangement is present between the columns and piers.
- External walls to building 1 are of solid reinforced concrete construction masonry infill and are considered to be load bearing. It appears as though additional steel columns have been added, which support additional steel beams, most likely as part of a seismic strengthening programme following the 2011 earthquakes.
- Building 2 has been constructed utilising a combination of pre-cast concrete panels, timber framed construction utilising a fibre cement board and monolithic cladding and painted masonry blockwork which has also been lined with monolithic cladding.
- We understand from landlord supplied information that the seismic ratings for the buildings sit between 70-76% although this has not been confirmed. The seismic report should be obtained for verification.

5 STRUCTURE

5.3 PHOTOGRAPHS



B1-Front elevation




B1- Concrete frame high level junction



B1- Tiled concrete sections



B1- Internal concrete goalpost support



B1- Internal lined column



B1- Concrete roof slab

5 STRUCTURE



B1- Canopy to south elevation



B1- Internal blockwork wall & pier



B2 – North elevation of original 1992 build



B2 - North elevation of 2007 extension



B2- Perimeter columns



B2- Internal columns arrangement

5 STRUCTURE



B2 – perimeter column



B2- Internal column

6 BUILDING FABRIC

6.1 SUMMARY OF ISSUES & OBSERVATIONS

Building 1

- Isolated live leaks were reported and also evidence of historic water ingress was identified below roof areas to the office floors. The roof areas are considered to be in fair condition and ongoing reactive maintenance of the roof can be observed. Although the roof is only causing relatively minor water ingress issues at present, we recommend this be budgeted for replacement within the long-term CapEx period.
- The following comments are made in relation to the roof:
 - We understand that the roof coverings were replaced approx. 5 years ago, along with the introduction of insulation creating a warm deck roof.
 - At the time of replacement roof coverings, a new metal walkway was installed, supported on plinths and housing a large satellite dish.
 - Although generally in fair condition, the roof has been subject to numerous patch repairs and ongoing repairs should be anticipated.
 - Joints to felt roofing starting to fail and sheets lifting at edges.
 - Gutters choking, surface water not draining and ponding to surface.
 - A number of areas were noted to be brittle and de-bonding from substrate which has led to bubbling of roof coverings and is likely to be a source of ongoing water ingress as sheet become brittle and cracks appear.
 - The Static line system is fitted to roof, although no tags were noted. We are unaware if this system has been de-commissioned.
 - Penetrations have been sealed with a liquid applied coating, this is for the most part cracked and worn and required to be re-coated.
- The façade overall is considered to be in good condition for its age, and we understand it is performing relatively well. No obvious visual defects were noted.
- We do not consider that any major works are required over the CapEx period other than standard routine maintenance and decoration. However, We recommend a façade inspection every 2 years over the reporting period.
- There is a risk of nickel sulphide inclusions in the toughened glass, however given the age of the asset, and lack of reported historic failures, the risk is considered to be low.
- Internal refurbishment has been implemented on a regular basis, this includes new tea prep/breakout area and office space fabric at suitable junctures. We make the following comments:
 - The level of finish where refurbished is of a good standard.
 - Un-refurbished elements are considered to be tired and dated. The refurbishment of these areas is subjective as the space is currently utilised as server rooms, plant rooms, storage cupboards etc therefore, we have made no allowance for refurbishment of these areas in the capex.
 - Amenities and kitchen areas have been largely upgraded.
 - A number of water damaged ceiling tiles are stained from previous water ingress and should be replaced.
- Cyclical repainting may be carried out in the long term if desired.

6 BUILDING FABRIC

Building 2

- No live leaks were reported although evidence of historic water ingress was identified below roof areas to the office floors. We understand that the leaks have been repaired, and the roof areas are considered to be in good condition and reactive maintenance to the roof can be observed. We do not expect any major works will be required over the CapEx reporting period over and above routine maintenance.
- The following comments are made in relation to the roof:
 - The roof coverings over 2007 extension are in good order and are 10 years old, the roof coverings over original 1992 building appear to have been replaced at the same time as the new extension was completed.
 - A metal stair and walkway was installed at time of extension to facilitate access between the two roofs.
 - The Static line system is fitted to roof, although no tags were noted. We are unaware if this system has been de-commissioned.
 - Repairs/seals at joints to cap flashings have been crudely completed and are likely to fail.
- The façade overall is considered to be in good condition for its age, and we understand it is performing relatively well. No obvious visual defects were noted.
- We do not consider that any major works are required over the CapEx period other than standard routine maintenance and decoration. However, we recommend a façade inspection every 2 years over the reporting period.
- There is a risk of nickel sulphide inclusions in the toughened glass, however given the age of the asset, and lack of reported historic failures, the risk is considered to be low.
- Internal refurbishment has been implemented to the original building on a regular basis, this includes upgrade of facilities at time of extension. We make the following comments:
 - The level of finish is of a good standard.
 - A number of water damaged ceiling tiles are stained from previous water ingress and should be replaced.
- Cyclical repainting may be carried out in the long/extended term if desired.

6.2 GENERAL DESCRIPTION

6.2.1 ROOFS

Building 1

- The main roof structure to the premises is a flat roof, comprising a concrete slab, overlaid with rigid insulation and covered with mineral felt flat roof coverings. The roof has a low-level parapet fitted with colour coated pressed metal parapet cap flashings.
- Surface water drains to recessed and concealed perimeter gutter, lined with mineral felt roof coverings and discharge to internally located downpipes. Outlets have been fitted with ball grates.
- Access onto the roof is via a fixed roof hatch within the fire scape stair located to the west side of the building. The access has been fitted with a fixed ladder which leads out on to new galvanised metal walkways which was installed when roof coverings were replaced.
- Static line fall protection system has been installed across the roof. Tags were not located on the system, making it unclear if the system has been de-commissioned. Clarification should

6 BUILDING FABRIC

be sought in this regard.

Building 2

- The main roof structure to the premises is a flat roof, comprising a concrete slab, overlaid with insulation and covered with single ply membrane flat roof coverings. The roof has a parapet wall dressed with single ply membrane roofing to inner face and over to external face. Parapet to original building has been fitted with metal cap flashings.
- Surface water drains to large recessed and concealed perimeter gutters, lined with single ply membrane roof coverings and discharge to internally located downpipes. Outlets have been fitted with ball grates.
- Access onto the roof is via an access door reached from stairwell from the reception lobby area. Fixed stairs have been fitted to facilitate access between different sections of roof.
- Roof plant is enclosed with louvred baffles, with gate fitted which provides access out on to the original part of building 2 from the access point.
- Static line fall protection system has been installed across the roof. Tags were not located on the system, making it unclear if the system has been de-commissioned. Clarification should be sought in this regard.

6.2.2 FACADES

Building 1

- The external walls are predominantly solid re-enforced concrete construction which have been painted, to the front elevation is a section of fixed curtain wall glazing. Sections of the concrete have been tiled, for decorative effect.
- Windows comprise single glazed metal framed windows, doors comprise a combination of aluminium framed glazed doors and solid core external timber doors which have been painted.
- An additional metal fire escape stair has been provided to south elevation, to meet increased occupancy requirements of the building.
- Above the main entrance doors to east and south elevations are metal framed barrel-vaulted canopy structures which has been lined with polycarbonate coverings.
- The building cores are predominantly constructed using a combination of masonry blockwork and timber framing lined with plasterboard linings to provide the minimum 1hr fire resistance.
- Internally the cores are finished with painted walls suspended ceilings and carpet floor coverings.
- The main entrance doors into the office foyer are aluminium framed glazed doors.
- Pedestrian doors are typically timber doors with timber frames and architraves.

Building 2

- The external walls are predominantly a combination of solid re-enforced concrete construction which have been painted, masonry or timber frame infill finished with a monolithic cladding. To the more recent extension is a section of glazed curtain wall system.
- Glazing is fixed aluminium framed single glazed window.
- The building cores are predominantly constructed using a combination of masonry blockwork and timber framing lined with plasterboard linings to provide the minimum 1hr fire resistance.
- Internally the cores are finished with painted walls and ceilings and painted concrete floor.

6 BUILDING FABRIC

- To the south west corner of the building and open deck area has been formed leading out from breakout area via glazed double doors. The deck area has been enclosed with an aluminium framed glazed balustrade and is finished with painted masonry and ceramic tile floor coverings.
- The main entrance doors into the entrance lobby are frameless automatic sliding doors with inner doors into reception foyer being aluminium framed glazed doors with standard push/pull handles and ironmongery.
- Pedestrian doors are typically a combination of aluminium framed glazed door and solid core timber doors. Door to fire escape at ground floor is not fitted with standard panic ironmongery.

6.2.3 INTERIOR

- As the buildings are 100% leased and occupied by the incumbent tenant, there are no common areas that are assessed as being the landlords' obligations to maintain.
- We understand from the current tenant, that the landlord has no responsibility for routine maintenance of the internal elements, however, we understand the landlord has responsibility for replacement of base build element when they are life expired, such as lighting, electrical, mechanical, carpets, suspended ceilings etc but not the internal partitions.
- Finishes to the interior of building 1 are of a good standard, with a combination of carpet and vinyl floor coverings, painted plasterboard walls and mineral fibre suspended ceiling system.
- Finishes to the interior of building 2 are of a good standard, with a combination of carpet and vinyl floor coverings, painted plasterboard walls and mineral fibre suspended ceiling system. We understand the landlord is responsible for replacing carpet will likely be required over the extended CapEx period and suspended ceilings which may be required
- We understand that building 2 was refurbished internally to include carpets and ceilings at the same time as the extension was built in 2007. This indicates that most of the finishes are approx.
- The original suspended ceiling system installed 1992 was not replaced as part of either the 2007 refurbishments and as such is considered to be in only fair condition although is unlikely to require replacement over the CapEx period.
- The buildings have various amenities to include male and female facilities which are located at various locations throughout the buildings. Finishes to the amenities include wall tiling, vinyl floor coverings and either painted plasterboard ceilings or suspended ceiling system. Amenities are generally in good condition and given the age of fittings and level of maintenance to date it is likely that replacement will be required in the extended CapEx period.
- Some of the amenities have been fitted with shower cubicles which appear functional and in good order.
- Within the plant room area to building 1 and garage area to building 2, no finishes are present. Concrete has been left exposed and not painted, no floor coverings or ceiling finishes are present.
- Stairwells are predominantly constructed using a combination of solid masonry blockwork and timber framed walls lined with plasterboard. Appropriate handrails utilised throughout.

6 BUILDING FABRIC

6.3 PHOTOGRAPHS



B1 - General view over roof



B1 - General view over roof




B1 - General view over roof



B1 - General view over roof



B1 – joints starting to lift at lapped edges



B1 – felt ruffled and de-bonded from substrate

6 BUILDING FABRIC



B1 – sealed junctions worn & solar degrading



B1 – choked outlet despite grate being fitted.



B1 – Liquid applied patch repair.



B2 - General view over roof to 2007 Ext



B2 – perimeter concealed gutter



B2 – standard drainage outlet

6 BUILDING FABRIC



B2 – flat roof over entrance lobby.



B2 – Patch repairs evident



B2 - General view over main building



B2 - General view over roof to 2007 Ext



B2 – Poor patch repairs to cap flashing joint



B2 – louvred plant enclosure

6 BUILDING FABRIC



B2 – plant on timber plinths



B2 – fixed stairs providing access over roofs



B2 – static line system.



B2 – typical anchor point



B1 – East elevation



B1 – West elevation

6 BUILDING FABRIC



B1 – south east corner



B1 – East elevation



B1 – Canopy & new external fire escape stair



B1 – New metal external fire escape stair



B1 – Double door out to hard standing



B2 – North elevation

6 BUILDING FABRIC



B2 – North elevation to modern extension



B2 – SW corner & semi enclosed deck area




B2 – SE corner



B2 – covered carport and garages




B1 – typical internal office




B1 – typical internal office


6 BUILDING FABRIC



B2 – Typical internal office



B2 – Typical internal office



B2 – Typical internal office



B2 – Internal fire escape stair



B2 – Stained & damaged ceiling tiles north end



B2 – Stained & damaged ceiling tiles north end

6 BUILDING FABRIC



B2 – semi enclosed deck area



B2 – WHB's in male amenities



B2 – accessible WC



B2 – Male amenities



B2 – tea prep/kitchen facilities



B2 – storage area to south end of building

7 EXTERNAL AREAS

7.1 SUMMARY OF ISSUES & OBSERVATIONS

- External areas were noted to be in good condition overall with no major works being identified.

7.2 GENERAL DESCRIPTION

- For the most part, the external areas comprise asphalt parking area providing numerous car parking spaces and vehicular access road to both buildings.
- Surrounding the car park are grassed areas, mature shrubs and trees. To the north-west corner is a concrete hard standing accessed from the break put room fitted with fixed seating.
- A standalone bike shed is positioned between the two buildings.
- Walkways are provided around some of the perimeter of the buildings, mostly completed in paving.
- The site is bounded by timber fences & chain link style fences fitted with razor wire on top, mature bushes and trees. Some of the fences are fitted with personnel gates which are fitted which are accessed via security swipe card access.
- To the south west corner of building 1 is a free-standing porta which is used to house plant. No access was gained at time of inspection.

7.3 PHOTOGRAPHS



Hard standing to NW corner of B1.



Chain-link perimeter fence & razor wire.

7 EXTERNAL AREAS



Grassed area to NW corner of B1.



Timber perimeter fence.



General view of parking area



General view of parking area



Bins store shed to SW corner of B1.



General view of parking area

7 EXTERNAL AREAS



General view of parking area



Bike store between buildings

8 MECHANICAL SERVICES

8.1 SUMMARY OF ISSUES & OBSERVATIONS

- The maintenance of the plant appears excellent and the general condition is good.
- System configuration appears to be a very apt application for the type of property. However, the systems are bespoke to the Tenant and will not suit another commercial tenant.
- Chillers will need to be replaced in the extended period
- The VESDA system and newly installed CRAC units are noted to be a tenant owned item and not under the responsibility of the landlord.
- The VRV systems appear in good condition and should not require attention until the latter parts of the extended period.
- The process cooling units appear to be in good condition but will require to be overhauled in the long term and extended CapEx period
- The outside air units will need to be overhauled in the long term.
- Ventilation systems will need some attention in the long term.
- There are individual packaged split units on the site that will need to be replaced as they fail.

8.2 GENERAL DESCRIPTION

- There are two distinctly different air conditioning systems serving the two buildings.
 - An air cooled chilled water system in each building that serves the mission critical rooms. These systems are backed up by equivalent air cooled packaged units.
 - A comfort air conditioning system of Daikin VRV plant that serves fan coils, cassettes, and wall hung units throughout the two building that provide comfort conditions for staff in offices, and incident rooms. The VRV systems have a preconditioned outside air supply from plant located on the roof.
 - There is also an array of split systems provided. Some units are owned by the Landlord and other by the Tenant. Refer to 8.3 Specific Mechanical Plant
- Andy Herd Building (AHB) (Building 1)
 - The chilled water plant is currently being refurbished with a new Aermec air cooled chiller being installed to replace and exist system that comprised two Multistack chillers and pumps. The Aermec chiller has an onboard hydronic kit of pumps. The chiller is located on the ground at the rear of the building.

Air conditioning units are computer room air conditioning units (CRAC) or process coolers from either Stultz or Emmerson. They are close control units designed specifically for high sensible cooling loads experienced in a computer facility.

Units are located on the floor in each critical space as well as two units in the ground floor plantroom with air ducted to the underfloor area of the room above.
 - The VRV system is Daikin with outdoor units located at ground level and the indoor evaporator units are located in individual rooms and spaces as required by the cooling demand.
 - Outside air to the VRV evaporators is supplied from the perimeter of the floors.
 - Split systems handle specific rooms and areas.
- Airways Development Centre (ADC) (Building 2)
 - The chilled water plant comprises three Aermec air cooled chillers that seem to be less than five years old. They are located on the roof of the building with the CRAC units located on

8 MECHANICAL SERVICES

the floor of the critical rooms.

- The VRV systems are Daikin with outdoor units located on the roof and the indoor evaporator units are located in individual rooms and spaces as required by the cooling demand.
- Split systems handle specific rooms and areas.
- Outside air is provided from two air handlers located on the roof that precondition the outside air.
- Extraction systems are provided in the larger operational rooms that seemingly are manually controlled to relieve heat from the room if the temperature rises. It is suspected the system was intended as a smoke relief in the event of a fire.
- There are several sundry ventilation systems provided for toilets, amenities, etc.

8.3 SPECIFIC MECHANICAL PLANT

The following list mechanical equipment installed in the two buildings. The lists are extracted from information provided:

| Unit | Type | Brand | Model | Location | Owner | Year |
|-------------|----------------------|------------|----------------|----------------------------|----------|------|
| ADC1 | | | | | | |
| AHU 01 | OA E/Cool | Breezeair | EA150S | Roof | Landlord | 1999 |
| AC 2 | Hi Wall | Mitsubishi | SRK63ZES1 | 1st Floor ADC UPS A Room | Landlord | 2007 |
| AC 3 | Hi Wall | Mitsubishi | SRK63ZES1 | 1st Floor Hot Standby Room | Landlord | 2007 |
| AC 4 | Hi Wall | Mitsubishi | SRK63ZK-S | 1st Floor ADC UPS A Room | Tenant | 2012 |
| AC 20 | Process cooler | Atlas | PEC 223FC | Equipment Room | Landlord | 1999 |
| AC 21 | Process cooler/ CRAC | Stulz | ASD361 | Equipment Room | Tenant | 2012 |
| AC 24 | Process cooler/ CRAC | Stulz | ASD361 | Equipment Room | Tenant | 2012 |
| FCU 1 | Ducted | Temperzone | RCMC 200 | ADC Reception | Landlord | 1999 |
| FCU 2 | Ducted | Temperzone | RCMC 150 | Meeting Room Alpha | Landlord | 1999 |
| FCU 3 | Ducted | Temperzone | RCMC 200 | Meeting Room Zulu | Landlord | 1999 |
| FCU 4 | Ducted | Temperzone | RCMC 200 | Breakout Room | Landlord | 1999 |
| FCU 5 | Ducted | Temperzone | RCMC 200 | Common Area / Café | Landlord | 1999 |
| FCU 6 | Ducted | Temperzone | RCMC 200 | Open Plan Office GND | Landlord | 1999 |
| FCU 7 | Ducted | Temperzone | RCMC 150 | Open Plan Office GND | Landlord | 1999 |
| FCU 8 | Ducted | Temperzone | DF 301 | Open Plan Office GND | Landlord | 1999 |
| FCU 9 | Ducted | Temperzone | DF 501 | Open Plan Office GND | Landlord | 1999 |
| FCU 10 | Ducted | Temperzone | DF 501 | Open Plan Office GND | Landlord | 1999 |
| FCU 11 | Ducted | Temperzone | RCMC 150 | Open Plan Office GND | Landlord | 1999 |
| FCU 12 | Ducted | Temperzone | RCMC 150 | Hot Standby Room | Landlord | 1999 |
| FCU 13 | Ducted | Temperzone | IMDL 130 | Network Office | Landlord | 2011 |
| FCU 14 | Ducted | Temperzone | RCMC 300 | Engineering Office | Landlord | 1999 |
| FCU 15 | Ducted | Temperzone | RCMC 300 | Network Office | Landlord | 1999 |
| FCU 16A | Ducted | Temperzone | IMD 95 | Radar Sim Pilot | Landlord | 2006 |
| FCU 16b | Ducted | Temperzone | IMD 95 | Radar Sim Pilot | Landlord | 2006 |
| FCU 17 | Ducted | Temperzone | DF 501 | Radar Sim Controllers | Landlord | 1999 |
| FCU 18 | Ducted | Temperzone | RCMC 300 | SIM Team Office | Landlord | 1999 |
| FCU 19 | Ducted | Temperzone | DF 701 | SIM Team Office | Landlord | 1999 |
| FCU 22 | Ducted | Temperzone | IMD 40 | Open Plan Office GND | Landlord | 2007 |
| EF 1 | Roof | Temperzone | 19IVJ | | Landlord | 2001 |
| EX Fan | Toilet | Woods | DSMR 330/4/1 | | Landlord | 1999 |
| EX Fan | Kitchen | Woods | DSMR 250/4/1 | | Landlord | 1999 |
| | Chiller | Aermec | NRL 280-700 FC | Roof | Landlord | 2013 |
| | CHWP | Wilo | IPN 65 | Roof | Landlord | 1999 |
| | CHWP | Wilo | IPN 65 | Roof | Landlord | 1999 |
| | EX Fan | S&P | HV-230-A-E | Lift Machine Room | Landlord | 1999 |
| | UPS B | Temperzone | ISD 181 | | Landlord | 2005 |

8 MECHANICAL SERVICES

| Unit | Type | Brand | Model | Location | Owner | Year |
|---------------------|---------------|------------|-------------|------------------------|----------|------|
| ADC2 | | | | | | |
| OU1 | Daikin VRV | REYQ42MYIB | OA for AC1- | | | |
| Ground Floor | | | | | | |
| AC1 | Ducted | Daikin | FXSQ63MVF | International | Landlord | 2007 |
| AC2 | Cassette | Daikin | FXFQ125MVE | Café - 1 | Landlord | 2007 |
| AC3 | Cassette | Daikin | FXFQ125MVE | Café - 2 | Landlord | 2007 |
| AC4 | Ducted | Daikin | FXSQ63MVE | Meeting Room/Visitors | Landlord | 2007 |
| AC5 | Ducted | Daikin | FXSQ40MVE | Meeting Room | Landlord | 2007 |
| AC6 | Ducted | Daikin | FXSQ63MVE | Training/Meeting Room | Landlord | 2007 |
| AC8 | Ducted | Daikin | FXSQ40MVE | Laboratory 1 | Landlord | 2007 |
| AC9 | Ducted | Daikin | FXSQ63MVE | Meeting Room/Visitors | Landlord | 2007 |
| AC 10 | Ducted | Daikin | FXSQ20MVE | Resource Room | Landlord | 2007 |
| AC 11 | Cassette | Daikin | FXFQ25MVE | Central Workshop 1 | Landlord | 2007 |
| AC 12 | Cassette | Daikin | FXFQ25MVE | Central Workshop 2 | Landlord | 2007 |
| AC 13 | Ducted | Daikin | FXSQ63MVE | Equipment Room | Landlord | 2007 |
| AC 13A | Hi-Wall | Mitsubishi | MASZ-GE71VA | Equipment Room | Tenant | 2012 |
| AC 14 | Cassette | Daikin | FXFQ25MVE | Meeting Room/Visitors | Landlord | 2007 |
| AC 15 | Ducted | Daikin | FXSQ63MVE | Open Plan Area | Landlord | 2007 |
| AC 16 | Hi-Wall | Daikin | FXAQ20MVE | Heavy Duty Workshop | Landlord | 2007 |
| AC 17 | Ducted | Daikin | FXSQ50MVE | Meeting Room | Landlord | 2007 |
| AC 18 | U/ceiling | Daikin | FXHQ32MVE | Supply Store - 1 | Landlord | 2007 |
| AC 19 | Ducted | Daikin | FXSQ100MVE | Nav Team | Landlord | 2007 |
| AC 20 | U/ceiling | Daikin | FXSQ100MVE | Supply Store - 2 | Landlord | 2007 |
| AC 21 | Ducted | Daikin | FXSQ63MVE | Drafting Office | Landlord | 2007 |
| AC22 | Ducted | Daikin | FXSQ25MVE | Meeting Room | Landlord | 2007 |
| AC 23 | Ducted | Daikin | FBQ50/RXS50 | MIS Help desk | Landlord | 2009 |
| AC 24 | Hi-Wall | Daikin | FXAQ20MVE | Supply Officer | Landlord | 2007 |
| AC 25 | Hi-Wall | Daikin | FTXS35GVMA | Supply Office | Landlord | 2009 |
| AC 55 | Ducted | Daikin | FXSQ40MVE | Laboratory - 2 | Landlord | 2007 |
| First Floor | | | | | | |
| OU2 | VRV | Daikin | REYQ40MYIB | Outdoor Unit for AC | Landlord | 2007 |
| OU3 | VRV | Daikin | REYQ42MYIB | Outdoor unit for AC | Landlord | 2007 |
| AC 1 | Cassette | Mitsubishi | | ADC Reception | Landlord | 2007 |
| AC 26 | Hi-Wall | Daikin | FXAQ20MVE | Requirements Manager | Landlord | 2007 |
| AC 27 | Hi-Wall | Daikin | FXAQ20MVE | Manager | Landlord | 2007 |
| AC 28 | Ducted | Daikin | FXMQ250MVE | Skyline & ATS | Landlord | 2007 |
| AC 29 | Ducted | Daikin | FXSQ125MVE | Large Office | Landlord | 2007 |
| AC 29A | Hi-Wall | Daikin | FXAQ20MVE | Small Office | Landlord | 2007 |
| AC 30 | Cassette | Daikin | FXFQ63MVE | Equipment Room | Landlord | 2007 |
| AC 31 | Cassette | Daikin | FXFQ63MVE | Equipment Room T19 | Landlord | 2007 |
| AC 31A | Under ceiling | Daikin | FHQ125 | Equipment Room T19 | Landlord | 2016 |
| AC 32 | Ducted | Daikin | FXSQ100MVE | Thales Office | Landlord | 2007 |
| AC 33 | Ducted | Daikin | FXSQ50MVE | Meeting Room | Landlord | 2007 |
| AC33 A | Under Ceiling | Daikin | FHQ71BV1B | Meeting Room | Tenant | 2011 |
| AC 33B | Hi-Wall | Daikin | FAQ100CVEA | Meeting Room | Tenant | 2015 |
| AC 33C | Hi-Wall | Daikin | FAQ100CVEA | Meeting Room | Tenant | 2015 |
| AC 34 | Cassette | Daikin | FXFQ63MVE | Equipment Room T8 | Landlord | 2007 |
| AC 34A | Under ceiling | Daikin | FHQ125 | Equipment Room T8 | Landlord | 2009 |
| AC 35 | Ducted | Daikin | FXSQ80MVE | Staff Room | Landlord | 2007 |
| AC 36 | Ducted | Daikin | FXSQ50MVE | Meeting Room | Landlord | 2007 |
| AC 37 | Cassette | Daikin | FXFQ32MVE | Reception | Landlord | 2007 |
| AC 38 | Hi-Wall | Daikin | FXAQ20MVE | Manager | Landlord | 2007 |
| AC 39 | Ducted | Daikin | FXSQ80MVE | Open Plan Office | Landlord | 2007 |
| AC 40 | Ducted | Daikin | FXSQ63MVE | Training & Development | Landlord | 2007 |
| AC 42 | Ducted | Daikin | FXSQ125MVE | Aerodrome Simulator 2 | Landlord | 2007 |
| AC 42A | Hi-Wall | Mitsubishi | MSZ-GE80VA | Aerodrome Simulator 2 | Tenant | 2012 |
| AC 43 | Cassette | Daikin | FXFQ32MVE | Simulator/Pilots Room | Landlord | 2007 |
| AC 44 | Cassette | Daikin | FXFQ125MVE | Simulator Equipment | Landlord | 2007 |
| AC 44A | Under ceiling | Daikin | FHQ100 | Simulator Equipment | Landlord | 2009 |

8 MECHANICAL SERVICES

| Unit | Type | Brand | Model | Location | Owner | Year |
|------------|-------------------------|-------------|-------------|----------------------------|----------|------|
| AC 44B | Under ceiling | Daikin | FHQ100 | Simulator Equipment | Landlord | 2009 |
| AC 45 | Cassette | Daikin | FXFQ32MVE | Simulator/Pilots Room | Landlord | 2007 |
| AC 46 | Ducted | Daikin | FXSQ125MVE | Class Room 3 | Landlord | 2007 |
| AC 47 | Ducted | Daikin | FXSQ125MVE | Aerodrome simulator – 1 | Landlord | 2007 |
| AC 47A | Hi-Wall | Mitsubishi | MSZ-GE80VA | Aerodrome simulator – 1 | Tenant | 2012 |
| AC 48A | Ducted | Daikin | FXSQ80MVE | Instructors Office | Landlord | 2009 |
| AC 48B | Ducted | Daikin | FXSQ80MVE | Instructors Office | Landlord | 2009 |
| AC 49 | Ducted | Daikin | FXSQ125MVE | Radar Suite | Landlord | 2007 |
| AC 50 | Cassette | Daikin | FXFQ63MVE | Radar Suite | Landlord | 2007 |
| AC 50A | Hi-Wall | Daikin | FAQ100BVV1B | Radar Suite | Tenant | 2012 |
| AC51 | Ducted | Daikin | FXSQ125MVE | Students Cafeteria | Landlord | 2007 |
| AC 52 | Ducted | Daikin | FXSQ125MVE | Classroom 4 | Landlord | 2007 |
| AC 53 | Ducted | Daikin | FXSQ125MVE | Classroom 2 | Landlord | 2007 |
| AC54 | Ducted | Daikin | FXSQ125MVE | Computer Laboratory | Landlord | 2007 |
| AC 56 | Hi-Wall | Daikin | FAQ100CVEA | Supply Store – 2 | Tenant | 2012 |
| AC 57 | Hi-Wall | Daikin | FTXS50 | PABX Room | Tenant | 2015 |
| AC 58 | Hi Wall | Daikin | FTXS60KAVMA | Radar Simulator ADC 1 | Landlord | 2013 |
| AC 59 | Hi Wall | Daikin | FTXS60KAVMA | Radar Simulator ADC 1 | Landlord | 2013 |
| AC 60 | Hi Wall | Daikin | FTXS60KAVMA | Radar Simulator ADC 1 | Landlord | 2013 |
| AC 61 | Cassette Daikin | Daikin | RZQ71KVEA | Skyline & ATS | Tenant | 2016 |
| AC 62 | Cassette Daikin | Daikin | RZQ71KVEA | Skyline & ATS | Tenant | 2016 |
| EF1 | Extract Fan | Fantech | CD566V | Kitchen Hood | Landlord | 2007 |
| EF2 | Extract Fan | Fantech | MV254E | Dishwasher | Landlord | 2007 |
| EF3 | Extract Fan | Fantech | CE404D | Store Extract | Landlord | 2007 |
| EF4 | Extract Fan | Fantech | CE456D | Main Toilet | Landlord | 2007 |
| EF5 | Extract Fan | Fantech | CE354D | Resource | Landlord | 2007 |
| EF6 | Extract Fan | Fantech | CE314D | South Toilets | Landlord | 2007 |
| AHU | Fresh Air | Sital Klima | RTSK-H | Roof | Landlord | 2016 |
| AHB | | | | | | |
| AC 1 | Process cooler/ CRAC | Liebert | PEX 2070 | Plant Room | Landlord | 2011 |
| AC 2 | Process cooler/ CRAC | Liebert | PEX 2070 | Plant Room | Landlord | 2011 |
| Atlas 8 | Process cooler/ CRAC | Atlas | 243 FC | Equipment Room | Landlord | 2002 |
| Atlas 9 | Process cooler/ CRAC | Atlas | 243 FC | Equipment Room | Landlord | 2002 |
| AC 1 | | Daikin | FXSQ25MVE | Sleeping Rooms | Landlord | 2009 |
| AC 2 | | Daikin | FXSQ50MVE | Quiet Room | Landlord | 2009 |
| AC 3 | | Daikin | FXSQ63MVE | Cafeteria | Landlord | 2009 |
| AC 4 | | Daikin | FXSQ63MVE | Cafeteria | Landlord | 2009 |
| AC 5 | | Daikin | FXSQ32MVE | Meeting Room Wigram | Landlord | 2009 |
| AC 6 | | Daikin | FXSQ50MVE | Governance Office | Landlord | 2009 |
| AC 7 | | Daikin | FXSQ40MVE | Governance Office | Landlord | 2009 |
| AC 8 | | Daikin | FXSQ32MVE | Standards Room | Landlord | 2009 |
| AC 9 | | Daikin | FXSQ25MVE | Governance Office | Landlord | 2009 |
| AC 10 | | Daikin | FXSQ25MVE | Technician Office | Landlord | 2009 |
| AC 11 | | Daikin | FXSQ25MVE | Technician Office | Landlord | 2009 |
| AC 12 | | Daikin | FXSQ63MVE | Technician Office | Landlord | 2009 |
| AC 13 | | Daikin | FXSQ40MVE | Technician Lab | Landlord | 2009 |
| AC14 | | Daikin | FXSQ63MVE | AHB Reception | Landlord | 2009 |
| FCU 1 | Ducted | Temperzone | IMDL 60 | Open Plan Office GND | Landlord | 1999 |
| FCU 2 | Ducted | Temperzone | IMDL 40 | Open Plan Office GND | Landlord | 1999 |
| FCU 3 | Ducted | Temperzone | IMDL 60 | Open Plan Office GND | Landlord | 1999 |
| FCU 4 | Ducted | Temperzone | IMDL 40 | Open Plan Office GND | Landlord | 2009 |
| FCU 5 | Ducted | Temperzone | IMD 280 | Open Plan Office GND | Landlord | 2004 |
| FCU 6 | Ducted | Temperzone | IMD 280 | Governance Office | Landlord | 2002 |
| FCU 7 | Ducted | Temperzone | IMDL 60 | Open Plan Office 1st Floor | Landlord | 2009 |

8 MECHANICAL SERVICES

| Unit | Type | Brand | Model | Location | Owner | Year |
|--------|------------|------------|------------|----------------------------|----------|------|
| FCU 8 | Ducted | Temperzone | IMDL 60 | Open Plan Office 1st Floor | Landlord | 2009 |
| FCU 9 | Ducted | Temperzone | IMDL 60 | Open Plan Office 1st Floor | Landlord | 2009 |
| FCU 10 | Ducted | Temperzone | IMD 210 | Meeting Room Rongotai | Landlord | 2002 |
| FCU 11 | Ducted | Temperzone | IMDL 90 | OCS Contingency Room | Landlord | 2009 |
| FCU 12 | Ducted | Temperzone | IMDL 130 | Notam Office | Landlord | 2009 |
| OAU 1 | | Daikin | FXMQ125MVE | FA South Entrance | Landlord | 2009 |
| OAU 2 | | Daikin | FXMQ200MVE | FA Cafeteria | Landlord | 2009 |
| | Package | Temperzone | OPA 100RKT | Portacom | Landlord | 2008 |
| | Hi Wall | Daikin | FTXS 25 | Portacom | Landlord | 2013 |
| | Hi Wall | Mitsubishi | MSZ A12 TV | Duty Manager Office | Landlord | 2005 |
| | Chiller | Aermec | | Outside | Landlord | 2017 |
| EF 1 | Roof | Temperzone | 19IVJ | ACC Smoke Extract | Landlord | 2001 |
| EF 2 | Roof | Temperzone | 19IVJ | Equipment Room S/Extract | Landlord | 2001 |
| F1 | Utility Rm | Woods | ICL/4 | Ground Floor | Landlord | 2009 |
| F2 | Toilet Ex | Woods | ILC 6 | Ground Floor | Landlord | 2009 |
| SPAF 1 | 1st Floor | Woods | 442558 | ACC | Landlord | 1989 |
| SPAF 2 | 1st Floor | Woods | 442558 | Open Plan Office 1st Floor | Landlord | 1989 |
| TExF1 | Toilet Ex | Woods | 442556 | Ground Floor | Landlord | 1989 |
| TExF1 | Toilet Ex | Woods | 442557 | 1st Floor | Landlord | 1989 |

8.4 PHOTOGRAPHS



New Aermec chiller waiting to be installed



Old Multistack chillers



Typical CRAC



Air cooled CRAC condensers

8 MECHANICAL SERVICES



Outside air preconditioner



Aermec chillers – ADC



Heat relief fans – (suspected of being smoke relief)



Ceiling hung split unit



Cassette unit



Outdoor units

9 ELECTRICAL SERVICES

9.1 SUMMARY OF ISSUES & OBSERVATIONS

- Electrical services appear to be well maintained and in very good condition.
- Main switchboard (MSB) and distribution boards (DB) are generally in good condition and should not require attention until the extended reporting period.
- Emergency power generators are tenant property and are virtually new and should not require attention outside normal maintenance within the reporting period.
- The UPS installations is the property of the tenant.
- Emergency lighting appears conforming but there is some need for additional exit signage to promote the egress paths.

9.2 GENERAL DESCRIPTION

- There are two 500kVA transformers feeding the site one is dedicated to the non-essential services in both buildings but with a manual changeover switching to allow the transformer to also feed essential services. The second is dedicated solely to essential services.
- Two Volvo 290kVA emergency power generators (EPG) supply the MSB. The EPG's are tenant property and are relatively new and are installed in plantrooms at the rear of the Andy Herd Building.
- There are Uninterruptable Power Supplies (UPS) in each building. The UPS is owned by the tenant and the capacity is unknown.
- All essential services supplies are configured as A & B supplies giving 100% redundancy or N+N.
- The main switchboard is located in the plantroom of building 1 as well as building 2. The MSB's are configured as A & B feeds that distribute power to the loads throughout the buildings.
- Distribution boards (DB) are located throughout the buildings. Some simply distribute light and general power while others are dedicated to specific tasks.
- Lighting is generally by twin tube fluorescent luminaires recessed in the ceiling.
- Emergency lighting and exist signage is provided.
- Security and access control is provided but that is a tenant asset.
- Communications facilities are extensive as is required by the nature of the building use.

9 ELECTRICAL SERVICES

9.3 PHOTOGRAPHS



Transformer



Transformer



MSB



UPS and Batteries (Tanat owned)



EPG 1 (Tenant owned)



Automatic transfer switch cabinet

9 ELECTRICAL SERVICES



EPG 2 (Tenant owned)



Distribution board – bespoke to the tenant



Typical DB



Typical lighting



Fuel facility for EPG (Tenant owned)



Typical DB

10 FIRE SERVICES

10.1 SUMMARY OF ISSUES & OBSERVATIONS

- Fire services appear in very good condition and well maintained.
- The FIP will need to be replaced in the long term and most probably in the extended period as well.
- Boosters and sprinkler valves will need to be overhauled in the long term and extended period.
- Hydrants will need overhaul in the long term and extended period.
- The sprinkler storage tank will need attention in the extended period.

10.2 GENERAL DESCRIPTION

- Fire services comprise:
 - Fire indicator panel (FIP) located in the foyer of building 1. The panel appears to be reasonably old.
 - Sprinklers throughout both buildings with booster connections and valves located at ground level. It was noted that wet sprinklers are also protecting the mission critical areas.
 - A storage tank at ground level for sprinklers in the building 1
 - Smoke detectors throughout the buildings.
 - Equipment rooms (Computers) are protected by VESDA early warning alarms which we understand is property of the Tenant.
 - Hosereels are located throughout the buildings.
 - Hydrants are provided throughout the buildings.

10.3 PHOTOGRAPHS



FIP



Booster connections

10 FIRE SERVICES



Sprinkler valve set



Sprinkler valve set



Storage tank



VESDA (Tenant owned)



Smoke detector



Sprinklers

11 HYDRAULIC SERVICES

11.1 SUMMARY OF ISSUES & OBSERVATIONS

- Hydraulic services appear in reasonable condition with reasonable maintenance.
- The two header tanks on the roof of the building will need to be replaced in the medium term.
- Hot water system will need to be replaced as they fail.

11.2 GENERAL DESCRIPTION

- Water is supplied to the building from street mains on Sir William Pickering Drive.
- Cold water is stored in two tanks on the roof of the Building 2. The tanks appear to provide head for the building.
- Storm water is gravity drains to street mains.
- Sewage is gravity drained to street mains.
- Hot water is generated locally by electric cisterns.

11.3 PHOTOGRAPHS



Cold water header tank



Typical hot water system

12 VERTICAL TRANSPORTATION SERVICES


12.1 SUMMARY OF ISSUES & OBSERVATIONS

- Both lifts are at the end of their economic life and while they should be overhauled or replaced in the short term they appear to be in a condition that should keep them viable until the medium term. When replacement is planned MRL lifts could be considered.

12.2 GENERAL DESCRIPTION

- There are two lifts on the site. One in each building.
 - The lift within building 2 is a F L Jones hydraulic lift serving two floors with a capacity of 2500kg or 36 people. The lift is from original construction.
 - Building 1 has a hydraulic lift serving two floors with a capacity of 780kg or 11 people.

12.3 PHOTOGRAPHS



B2 - lift



B2 - lift car



B1 - lift



B1 - lift car



B2 - oil tank & pump



B1 - oil tank & pump

ATTACHMENT 1 CAPITAL EXPENDITURE REPORT

Our cost estimates associated with due diligence are generally concerned with capital expenditure (CAPEX) forecasts, normally reflecting a 10 year planning period, however as per specific request a 25 year CAPEX forecast has been included.

Hence, these estimates are indicative only and are provided as an “order of magnitude cost allowance” for specifically identified works. Items of work are often not fully described or detailed reflecting the high-level nature of the assessment, the amount of information available, a reasonable course of action, and the purpose for which they are prepared. We will consider and review any pre-existing CAPEX records or budgets, where they are made available.

Our CAPEX forecast also includes deferred repairs and maintenance (R&M) items which ought to have been carried out or should be planned for as a preventive measure. Routine repairs, maintenance and typical operational costs associated with the normal occupation and management of the asset are excluded unless otherwise stated.

Our costs are a present day estimate for undertaking the works as a stand-alone project and do not include the following (unless otherwise stated):

- preliminaries, builders’ margins, overheads or contingencies;
- negotiated, staged or other special forms of contract;
- approval, consents or compliance orders;
- costs associated with the further investigations;
- professional/consultant fees for further investigation and testing, the design, documentation and the management of rectification works, or any resulting change in the scope of rectification works;
- costs associated with the relocation, temporary accommodation, disruption to business or loss of profit of the building owner or tenants;
- work outside site boundaries;
- work outside normal business hours;
- goods and services tax (GST); and
- future escalation.

Our cost estimates have been assessed on the basis of their likelihood (i.e. how likely is it that it will occur) and consequence (what is the impact if the event does occur). These two values are combined to give an overall ‘risk rating’ which as per the table below:

| Likelihood | Consequence | | | | |
|----------------|---------------|----------|----------|----------|--------------|
| | Insignificant | Minor | Moderate | Major | Catastrophic |
| Almost Certain | Low | Moderate | High | High | High |
| Likely | Low | Moderate | Moderate | High | High |
| Possible | Low | Low | Moderate | High | High |
| Unlikely | Low | Low | Moderate | Moderate | High |
| Rare | Low | Low | Low | Moderate | High |



CAPITAL EXPENDITURE (CAPEX) FORECAST
20-28 SIR WILLIAM PICKERING DRIVE, BURNSIDE, CHRISTCHURCH, NZ

SUMMARY OF COSTS

SUMMARY BY ELEMENT

| | Immediate (within 1 year) | Short Term (1-2 Years) | Medium Term (3-5 Years) | Long Term (6-10 Years) | Extended Term (11-25 Years) | Total |
|-------------------------|------------------------------|---------------------------|----------------------------|---------------------------|--------------------------------|---------------------|
| STRUCTURE | \$ - | \$ - | \$ - | \$ - | \$ 15,000 | \$ 15,000 |
| BUILDING FABRIC | \$ 3,500 | \$ - | \$ - | \$ - | \$ 1,400,000 | \$ 1,403,500 |
| EXTERNAL AREAS | \$ - | \$ - | \$ - | \$ - | \$ 25,000 | \$ 25,000 |
| MECHANICAL SERVICES | \$ - | \$ - | \$ - | \$ 175,000 | \$ 983,000 | \$ 1,158,000 |
| ELECTRICAL SERVICES | \$ - | \$ 5,000 | \$ - | \$ - | \$ 300,000 | \$ 305,000 |
| FIRE SERVICES | \$ - | \$ - | \$ - | \$ 45,000 | \$ 70,000 | \$ 115,000 |
| HYDRAULICS SERVICES | \$ - | \$ - | \$ 20,000 | \$ 10,000 | \$ 20,000 | \$ 50,000 |
| VERTICAL TRANSPORTATION | \$ - | \$ - | \$ 180,000 | \$ - | \$ 180,000 | \$ 360,000 |
| TOTAL | \$ 3,500 | \$ 5,000 | \$ 200,000 | \$ 230,000 | \$ 2,993,000 | \$ 3,431,500 |

SUMMARY BY WORK TYPE

| | Immediate (within 1 year) | Short Term (1-2 Years) | Medium Term (3-5 Years) | Long Term (6-10 Years) | Extended Term (11-25 Years) | Total |
|--------------|------------------------------|---------------------------|----------------------------|---------------------------|--------------------------------|---------------------|
| R&M | \$ 1,000 | \$ - | \$ - | \$ 85,000 | \$ 270,000 | \$ 356,000 |
| CAP | \$ 2,500 | \$ 5,000 | \$ 200,000 | \$ 145,000 | \$ 2,723,000 | \$ 3,075,500 |
| TOTAL | \$ 3,500 | \$ 5,000 | \$ 200,000 | \$ 230,000 | \$ 2,993,000 | \$ 3,431,500 |

SUMMARY BY RISK RATING

| | Immediate (within 1 year) | Short Term (1-2 Years) | Medium Term (3-5 Years) | Long Term (6-10 Years) | Extended Term (11-25 Years) | Total |
|--------------|------------------------------|---------------------------|----------------------------|---------------------------|--------------------------------|---------------------|
| HIGH | \$ - | \$ 5,000 | \$ - | \$ - | \$ - | \$ 5,000 |
| MODERATE | \$ 2,500 | \$ - | \$ 200,000 | \$ 230,000 | \$ 2,468,000 | \$ 2,900,500 |
| LOW | \$ 1,000 | \$ - | \$ - | \$ - | \$ 525,000 | \$ 526,000 |
| TOTAL | \$ 3,500 | \$ 5,000 | \$ 200,000 | \$ 230,000 | \$ 2,993,000 | \$ 3,431,500 |



CAPITAL EXPENDITURE (CAPEX) FORECAST

20-28 Sir William Pickering Drive, Burnside, Christchurch, NZ

| Item | Element / Description / Location | Suggested Remedy | Work Type | Likelihood | Consequence | RISK | Immediate | Short Term (1-2 Years) | Medium Term (3-5 Years) | Long Term (6-10 Years) | Extended Term (11-25 years) | Total |
|------------------------------|--|--|-----------|------------|---------------|----------|-----------|------------------------|-------------------------|------------------------|-----------------------------|------------|
| 1 STRUCTURE | | | | | | | | | | | | |
| 1.1 | No major concerns identified. | None required currently although allowance to be made for full inspection in the extended period. | CAP | Possible | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 15,000 | \$ 15,000 |
| 2 BUILDING FABRIC | | | | | | | | | | | | |
| 2.1 ROOFS | | | | | | | | | | | | |
| 2.1.1 | Felt roof to building 1 will require replacement in the long term. | Replace felt roof coverings to building 1. | CAP | Possible | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 135,000 | \$ 135,000 |
| 2.1.2 | Static line anchor system has no tags. | Have system assessed and signed off or decommissioned | CAP | Possible | Moderate | Moderate | \$ 2,500 | \$ - | \$ - | \$ - | \$ - | \$ 2,500 |
| 2.1.3 | Single ply membrane to Building 2. | increased maintenance anticipated in the extended term | CAP | Possible | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 75,000 | \$ 75,000 |
| 2.2 FACADES | | | | | | | | | | | | |
| 2.2.1 | No major concerns identified. | None required. | | | | | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 2.2.2 | Glazed curtain walling | Allow sum for overhaul of gaskets, joints and perishable items etc | R&M | Possible | Minor | Low | \$ - | \$ - | \$ - | \$ - | \$ 10,000 | \$ 10,000 |
| 2.2.3 | External decoration | Redecorate all external surfaces. | R&M | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 150,000 | \$ 150,000 |
| 2.3 INTERIOR | | | | | | | | | | | | |
| 2.3.1 | No major concerns identified. | None required. | | | | | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 2.3.2 | Water damaged ceiling tiles. | Replace all water damaged ceiling tiles. | R&M | Likely | Insignificant | Low | \$ 1,000 | \$ - | \$ - | \$ - | \$ - | \$ 1,000 |
| 2.3.3 | Carpet/vinyl floor coverings. | Replace carpet/vinyl floor coverings to all buildings at end of economic life | CAP | Likely | Minor | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 515,000 | \$ 515,000 |
| 2.3.3 | Suspended ceiling system | Replace suspended ceiling system at end of economic life | CAP | Possible | Minor | Low | \$ - | \$ - | \$ - | \$ - | \$ 515,000 | \$ 515,000 |
| 3 EXTERNAL AREAS | | | | | | | | | | | | |
| 3.1 | No major concerns identified. | Allow sum for carpark/road repairs in the extended term. | R&M | Likely | Minor | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 25,000 | \$ 25,000 |
| 4 MECHANICAL SERVICES | | | | | | | | | | | | |
| 4.01 | Chillers | New plant currently being installed but will need to be replaced in the extended period due to refrigerant legislation | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 150,000 | \$ 150,000 |



CAPITAL EXPENDITURE (CAPEX) FORECAST

20-28 Sir William Pickering Drive, Burnside, Christchurch, NZ

| Item | Element / Description / Location | Suggested Remedy | Work Type | Likelihood | Consequence | RISK | Immediate | Short Term (1-2 Years) | Medium Term (3-5 Years) | Long Term (6-10 Years) | Extended Term (11-25 years) | Total |
|--------------|----------------------------------|---|-----------|------------|-------------|----------|-----------------|------------------------|-------------------------|------------------------|-----------------------------|---------------------|
| 4.02 | Chillers | Replace the Aermec chiller in AHB | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 100,000 | \$ 100,000 |
| 4.03 | Process Cooling / CRAC Units | CRAC units appear in good condition but will need overhauled in the long and extended term. | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ 100,000 | \$ 350,000 | \$ 450,000 |
| 4.04 | VRV air conditioning plant | VRV plant appears in good condition, practically new. Replacement will be needed in the extended reporting period. Costs based on 91.5% landlord ownership. | CAP | Possible | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 183,000 | \$ 183,000 |
| 4.05 | OA units | Overhaul in the long term | R&M | Likely | Minor | Moderate | \$ - | \$ - | \$ - | \$ 40,000 | \$ 40,000 | \$ 80,000 |
| 4.06 | Ventilation systems | Ventilation systems such as toilets, amenities, etc, will need attention within the reporting period | CAP | Likely | Minor | Moderate | \$ - | \$ - | \$ - | \$ 10,000 | \$ 10,000 | \$ 20,000 |
| 4.07 | Other packaged AC plant | Replace as the units fail | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ 25,000 | \$ 150,000 | \$ 175,000 |
| 5 | ELECTRICAL SERVICES | | | | | | | | | | | |
| 5.01 | MSB's | Overhaul at the end of economic life | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 100,000 | \$ 100,000 |
| 5.02 | DB's | Overhaul at the end of economic life | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ - | \$ 200,000 | \$ 200,000 |
| 5.03 | Emergency lighting | Appears acceptable and conforming | | | | | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 5.04 | Exit signage | Some concerns with exit signage locations | CAP | Likely | Major | High | \$ - | \$ 5,000 | \$ - | \$ - | \$ - | \$ 5,000 |
| 6 | FIRE SERVICES | | | | | | | | | | | |
| 6.01 | FIP | Replace at the end of economic life | R&M | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ 25,000 | \$ 25,000 | \$ 50,000 |
| 6.02 | Boosters and Valve sets | Overhaul in the long term | R&M | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ 10,000 | \$ 10,000 | \$ 20,000 |
| 6.03 | Hydrants | Overhaul in the long term | R&M | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | \$ 10,000 | \$ 10,000 | \$ 20,000 |
| 6.04 | Sprinkler tank | Replace the tank in the extended period | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ - | | \$ 25,000 | \$ 25,000 |
| 7 | HYDRAULICS SERVICES | | | | | | | | | | | |
| 7.01 | Water header tanks | Replace the tanks on the roof | CAP | Likely | Minor | Moderate | \$ - | \$ - | \$ 10,000 | \$ - | \$ - | \$ 10,000 |
| 7.02 | Hot water systems | Replace as they fail | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ 10,000 | \$ 10,000 | \$ 20,000 | \$ 40,000 |
| 8 | VERTICAL TRANSPORTATION | | | | | | | | | | | |
| 8.01 | Lifts | Overhaul at the end of economic life. | CAP | Likely | Moderate | Moderate | \$ - | \$ - | \$ 180,000 | \$ - | \$ 180,000 | \$ 360,000 |
| TOTAL | | | | | | | \$ 3,500 | \$ 5,000 | \$ 200,000 | \$ 230,000 | \$ 2,993,000 | \$ 3,431,500 |

ATTACHMENT 2 EXCLUSIONS & QUALIFICATIONS

Although we will undertake as thorough and detailed an inspection as possible, our report will be subject to the following standard limitations.

- Parts of the building built in, covered up or otherwise made inaccessible during the inspection have not been inspected. This generally relates to ceiling voids, wall cavities and service risers. Therefore, we are unable to comment as to whether such elements are free from defect or infestation.
- Areas or building components that are covered up or permanently enclosed will not be inspected. Where risks exist in this regard, we will point these out and recommend opening up of the structure or fabric where this is merited to inspect such areas.
- As part of a typical survey inspection we endeavour to inspect all roof areas where safe access was provided, facades from ground level or other safe vantage points, the principle base building plant rooms and back of house areas and a reflective sample of the common areas and lettable office areas.
- Where a variety of multiple units are inspected, a random selection of each type of unit was inspected and used for the basis for this report. We have not prepared an exhaustive list of those minor defects or imperfections thought not to have a material bearing upon the proposed interest.
- We have not undertaken any work of a specific engineering nature, such as engineering calculations, structural analysis, testing or measurements as the report reflects our interpretation of the condition of the building as apparent from the inspection.
- Building services have been visually inspected where exposed to view only. No internal inspections have been undertaken of plant, equipment and machinery or where services are covered up or hidden by the building structural element or finishes. Building services have not been tested and no design calculations have been undertaken. If it is thought that a specific service or building element requires further testing or inspection, we will advise of this requirement. Further fees may be chargeable for these services if the visual inspection identifies areas of concern that require further intrusive investigation.
- The property has not been inspected specifically for termite infestation and we would only report on such if termite evidence was apparent during our inspection.
- This report is not a certification, a warranty or guarantee and has been scoped in accordance with the instructions given and the time allowed.
- The scope of the report is described within the body of this proposal and disciplines not specifically mentioned are excluded from this report.
- The report has been prepared for the benefit of the instructing entity only. This report is not to be reproduced, in whole or in part, without the express written authorisation of CBRE. The report may not be relied upon by any third party.
- No allowance has been made to provide vertical access equipment to allow for safe inspection of the roof. If there is a requirement for vertical access equipment, the cost will be charged in addition to the agreed fee. A 15% surcharge will apply.
- In regard to the services portion of this report, we have assumed that the services associated with the existing internal fit out are the tenant's responsibility and as such are not to be included within our review.
- Within this report, unless otherwise stated, we have commented on the condition of the property at the time of our inspection only, and we cannot guarantee that the property may be subject to damage or other adverse event following our inspection.
- Our investigation and report does not waive or relieve the project design team or contractor from their statutory and design obligations under their respective contracts.

ATTACHMENT 3 TERMS & CONDITIONS

In this Attachment:

Company means CBRE (A) Pty Limited ACN.

GST and Tax Invoice have the meanings given to those terms in A New Tax Systems (Goods and Services) Tax 1999

1. Instructing Party's Obligation to Assist

The Instructing Party agrees to provide all reasonable assistance to the Company to allow the Company to complete this instruction including providing all relevant documents and/or information the Instructing Party knows or ought reasonably to know will so assist the Company, at its own cost and in a timely fashion, including but not limited to:

- all information which the Company requests from time to time for the performance of the Services;
- reasonable access to the property/properties and to the Instructing Party's premises (if relevant) for the purpose of providing the Services.

The Instructing Party warrants that such information is complete and accurate.

2. Fees and Disbursements

The Company is entitled to be paid the Agreed Fee and the disbursements by the Instructing Party in consideration of the Company performing the Services.

The Company may invoice the Instructing Party for its reasonable out of pocket expenses incurred by the Company in the provision of the Services including travel, subsistence and document handling costs such as courier charges.

The Instructing Party must pay each Tax Invoice issued to it by the Company within 14 days of the date that the Instructing Party issues the Tax Invoice. A late payment fee of 2% per month (or part thereof) for any overdue amount may be charged by the Company.

All legal and debt recovery costs which the Company may incur in recovering overdue account balances from the Instructing Party will be fully recoverable from the Instructing Party as and when incurred.

3. Suspension of Services

The Company has the right to suspend its engagement where the Instructing Party fails to pay any invoiced fees and disbursements within the required time frame, by giving the Instructing Party seven days' notice in writing.

Should the engagement be suspended by the Company, all obligations by the Company to the Instructing Party cease to exist and, furthermore, all intellectual property that the Company receives from the Instructing Party prior to the engagement being suspended becomes the property of the Company and, unless otherwise agreed, the Company shall be free to use this information and value the property for any other party.

4. Return of Document

The Instructing Party agrees that the Company keep all papers and documents until the Agreed Fee and disbursements have been paid.

5. Intellectual Property

Any pre-existing intellectual property, which is recognised under any law, Copyright in any written work, drawing, compilation, table, graph and similar works created by or on behalf of the Company belongs to the Company.

6. Variation

The Terms of Engagement may only be varied in writing by mutual agreement of the parties.

7. Privacy Act

Any personal information collected and held by the Company in the course of providing the Services will only be used for purposes relating to the provision of services. More information about the manner in which the Company handles personal information is described in its privacy policy.

8. Assumptions and Reliance

The Instructing Party acknowledges that the Company:

- (a) will not verify the accuracy or completeness of information or materials provided to the Company;
- (b) the Services and any materials produced in the course of providing the Services are for the benefit of the Instructing Party and may not be relied on by any other party.

9. Indemnity

The Instructing Party indemnifies the Company against any liability, expense, loss, damage and cost in connection with a breach of the warranty given to the Company in paragraph 2.

ATTACHMENT 3 TERMS & CONDITIONS

10. Termination

Either party may terminate the Terms of Engagement by giving the other party at least 30 days' notice.

11. Current

Any materials including reports prepared in the course of the Services are current at the date of the production of the materials or date of report.

12. GST

Unless otherwise stated, all amounts payable are exclusive of GST. GST is payable by the Instructing Party in addition to the Agreed Fee, disbursements and any other moneys payable under the Terms of Engagement and the GST is payable at the same time as the amounts under the Company's Tax Invoice is payable.

13. Survival

Paragraphs 2 & 10 survive termination of the Terms of Engagement.

14. Assignment

The Instructing Party may not assign, novate, subcontract or transfer any part of this Terms of Engagement.

15. Application of clause

This paragraph 16 does not exclude or modify any condition or warranty implied into this Agreement, or any liability imposed on the Company, by law (including under the Trade Practices Act 1974 (Cth)), if to do so would contravene the law or make any part of this paragraph 16 void.

16. Exclusion of implied conditions and warranties

Subject to paragraph 16 the Company:

- (a) excludes any condition or warranty implied into this Terms of Engagement; and
- (b) limits its liability for breach of any implied condition or warranty that it cannot exclude to resupplying the Services, or paying the cost of having those services resupplied.

17. Entirety of Terms of Engagement

These Terms of Engagement:

- a) constitute the entire understanding and agreement of the parties relating to the matters dealt within in;
- b) supersedes and extinguishes all prior agreements, statements, representations and understandings whether verbal or written between us relating to and the Services;

- c) is confidential (except where required to be disclosed by law).

18. Limitation of Liability

The Company accepts no responsibility or liability whatsoever for the Services unless full disclosure of all information likely to affect the valuation has been made.

Conditions, warranties or other rights for the Instructing Party's benefit may be implied or given in respect of these terms and conditions by Competition and Consumer Act 2010 (Cth), the Fair Trading Act 1986 (NZ) (as relevant) or other laws. Where it is not lawful or possible to exclude them, then those conditions, warranties or other laws apply but only to the extent required by law.

All other implied conditions, warranties and rights together with any implied by custom or other circumstances are excluded.

The Company limits its liability for breach of any implied condition, warranty or right to the extent allowed by law. Subject to the qualifications in the Competition and Consumer Act 2010 (Cth) or in other laws, the Company's liability for any breach of any such implied condition, warranty or right is limited in the case of services supplied to one of the following as the Company may determine:

- the supplying of the Services again; or
- the payment of the cost of having the Services supplied again.

Subject to the provisions of this clause and despite any implication arising from any other clauses of this agreement, the Company is not liable in contract or in tort for or in respect of any direct or indirect loss or damage suffered by the Instructing Party or any other person arising out of any breach or other act or omission in connection with its engagement, or for the acts or omissions, or any loss caused thereby, of the environmental consultant or any other sub-contractors used in the course of providing the Services.

Indirect loss includes, without limitation, any financial loss or expense including where caused by loss of use or of goodwill, loss of data or delay in the performance of any obligation together with any expense incurred in connection with that loss or in litigation or attempted litigation of that loss.